Verizon 1300 I Street, N.W. Washington, D.C. 20005 Voice 202 336-7892 Fax 202 336-7922 Shawn Donnelly Staff Manager - Federal Regulatory



August 15, 2000

Mr. Dale Hatfield Chief – Office of Engineering and Technology Federal Communications Commission 445 12th Street, SW Room 7-C155 Washington, DC 20554

Re: Final Service Outage Report

Dear Mr. Hatfield:

In accordance with the requirements in CC Docket 91-273, enclosed is the Final Service Disruption Report for the Verizon service outage that occurred on July 19, 2000 affecting Pottstown, Pennsylvania.

Please call me if you have any questions about this report or other service outage issues.

Sincerely,

Enclosure

cc: R. Kimball

WIRE LINE OUTAGE REPORTING TEMPLATE

Reporting Carrier	Date of Incident
Verizon	07/19/2000
Time of Incident	Geographic Area Affected
09:19 AM	Pottstown, Pennsylvania
Services Affected	Number of Customers Affected
	Approximately 1200
IntraLATA Intraoffice X	Number of Blocked Calls
IntraLATA Interoffice X	Not applicable
InterLATA Interoffice X	Outage Duration
,	35 Hrs 41 Min
E911	
Background of the Incident	
On Wednesday, July 19 at 9:19 AM, a car struck	a utility pole and burst into flames, burning two
copper cables (total 1200 working pairs) and one	e interoffice fiber cable. The fiber cables serves
27 T3's of which all but 7 T3's between Pottstov	am and Panding switched to protection. Verizon
technicians received alarms in both these Centra	
Operations Center/Transport Management (NOC	C/TM) located spare fibers and began to patch
the T3's. Service to all 7 of the T3's was restore	d by 15:15 PM.
After the Fire Department had doused the fire, the	ne nower company had to replace both the pole
and their power cables. After the power company	
and their power cables. After the power compan	y completed their repairs around 16.00 Fivi,
Verizon construction began to replace and re-spl	ice the cables and service was fully restored by
Thursday, July 20 at 21:00 PM.	
Direct Cause	
External Environment	
Root Cause	
Vehicular Accident/Fire	·
Name and Type of Equipment	Specific Part of the Network Involved
2 copper and 1 fiber cables	Outside Plant Cable
Methods Used to Restore Service	
The damaged cables were replaced and spliced a	after the T3's were patched to spare facilities.
	·
Steps Taken to Prevent Recurrence of the Incident	
Stops Turbin to Trevent Accountance of the Interest.	
Dell Atlantic has no year to provent such inciden	***
Bell Atlantic has no way to prevent such inciden	us.
Evaluation of Best Practices	
	•
Not Applicable	
Contact Person	Telephone Number of Contact Person
Shawn Donnelly	202-336-7892

00-112

BELL ATLANTIC FCC NETWORK DISRUPTION INITIAL REPORT

TICKET #: 94G-LZ7

2.	DATE AND T	INE OF INC	IDENT:	07/19/	2000	
	GEOGRAPH	ic area af	FECTED:	Pottstown, PA	2000	01:22:00 PM
3.	MAXIMUM N	UMBER OF	CUSTOMER	S AFFECTED:	1200	
4.	TYPE OF SE				1200	
``\ =						
ixi in	MERGENCY-SERV NTRALATA	ICE IX INTER] OTHER		
5,	DURATION O	FOUTAGE:	Ongoing	3		
5.	ESTIMATED N	UMBER OF	BLOCKED	CALLO		oot Cause Analysis
'A.	TYON FALLEN				itermined at R	oot Cause Analysis
u.	TYPE EQUIPM	ENT: Cop	per Span	VENDO	R:	
ustor	mers	ie and caught	on fire which	set the pole on fire	i, burning cabi	es and affecting over 1,
•	METHOD USED	TO RESTO	RE SERVIC	E:		
	STEPS TAKEN To be determined	TO PREVEN at Root Cause	IT RECURR	ENCE;		
ursu Priid Paso	STEPS TAKEN To be determined ant to Section 0.4 lentiality is reques n for confidential	TO PREVEN at Root Cause 59 (b) of the sted for item ity:	IT RECURR Analysis Commissions:	ENCE: on Rules, and fo		
ursu enfid	STEPS TAKEN To be determined ant to Section 0.4 lentiality is reques n for confidential	TO PREVEN at Root Cause 59 (b) of the sted for item ity:	IT RECURR Analysis Commissions:	ENCE: on Rules, and fo		
ursu: onfid easo A Re bmit	STEPS TAKEN To be determined ant to Section 0.4 lentiality is reques in for confidential equest to supplements st Supplement:	TO PREVEN at Root Cause 59 (b) of the sted for item ity:	T RECURR Analysis Commissions:	ENCE: on Rules, and fo		t forth below, hereby made and wi
ursu: onfid easo A Re bmit	STEPS TAKEN To be determined ant to Section 0.4 lentiality is reques in for confidential equest to supplemented expeditiously	TO PREVEN at Root Cause 59 (b) of the sted for item ity:	T RECURR Analysis Commissions:	ENCE; on Rules, and fo sted by section		
A Resolution	STEPS TAKEN To be determined ant to Section 0.4 lentiality is reques in for confidential equest to supplements st Supplement:	TO PREVEN at Root Cause 59 (b) of the sted for item ity: ment the sho	T RECURR Analysis Commissions: wing reques	ENCE: on Rules, and fo sted by section	0.459 (b) is	